



S.I. M20-56
DATE 5-11-81

SUBJECT: KFC-200 AUTOMATIC FLIGHT CONTROL SYSTEM (AFCS) - PLACARDS

MODELS/S/N AFFECTED: Mooney Model M20J and M20K with King KFC-200 AFCS Installed

TIME OF COMPLIANCE: At next scheduled inspection.

INTRODUCTION: Some of the KFC-200 installation packages as received from King did not contain a complete set of placards as described in the Flight Manual Supplement. The possibility of the "▼ DISC AP" placard not being installed on the left horn of the pilot's control wheel does exist. If this placard is not present, proceed per the instructions below.

INSTRUCTIONS: At the next scheduled maintenance inspection the placard "▼ DISC AP" should be placed into position above and between the trim switch and the existing "MIKE" placard on the pilot's wheel. The "MIKE" placard may need to be moved forward and both placards trimmed to fit in the specified area. Refer to aircraft Flight Manual Supplement for proper operation of the "▼ DISC AP" switch.

REFERENCE DATA: 1. Approved Flight Manual Supplement on King KFC-200 Autopilot System

PARTS LIST: Kit No. S.I. M20-56-001

	Qty.	P/N	Description
1.	1	150080-338	Placard, "▼ DISC AP"
2.	1	150080-329	Placard, "MIKE"

FIGURES/TABLES: N/A