



SERVICE INSTRUCTION M20-118

Date: February 28, 2011

**SUBJECT:** TO ADVISE OWNERS OF THE INSPECTION OF ALL INTERIOR BOOTS - RUDDER, AILERON, FLIGHT CONTROL AND JOHNSON BAR BOOTS (if Applicable) WHEN SERVICE AND MAINTENANCE IS PERFORMED ON ALL MOONEY AIRCRAFT.

**MODELS/ SN  
AFFECTED:** All M20 thru M20TN Series Aircraft

**TIME OF  
COMPLIANCE:** Time of Service and Maintenance

**INTRODUCTION:** There has been a reported instance in the field, that an aircraft's "Johnson Bar" boot had a tear which allowed a small flashlight to interfere with the flight controls.

**INSTRUCTIONS:** This information is to re-emphasize the importance of inspecting all of the interior boots and covers to prevent objects or debris interfering with flight controls as well as the practice of keeping the aircraft clean from loose items or debris.

**WARRANTY:** N/A

**REFERENCE  
DATA:** Refer to Mooney Airplane Company Service Manuals (applicable A/C).

**PARTS LIST:** N/A

<u>Item</u>	<u>P/N</u>	<u>Description</u>	<u>QTY</u>
-------------	------------	--------------------	------------